

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
911 Safety Equipment LLC 329 E. Main Street Norristown, PA 19401	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier
Alberta Fire Gear Cleaning Ltd. 4826 B Hankin Street Thorsby AB T0C 2P0	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Associated Fire Safety Maintenance #106 – 3070 Norland Ave Burnaby BC V5B 3A6	Outer Shell Thermal Liner WL Gore Crosstech 2 Layer Type 2C Moisture Barrier WL Gore Black Crosstech Type 2F Moisture Barrier WL Gore RT7100 Type 3D Moisture Barrier
Bay Area Gear Repair 5910 Pine Hill Road Port Richey, FL 34668	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner Stedfast Stedair 3000 Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier
Choice Clean Gear LLC 369 Turner Industrial Way Aston, PA 19014	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
City of Kirkland (Organization) 123 5th Ave. Kirkland, WA 98033	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier
D & D Mountain Air Cleaners 309 South Paseo De Onate Espanola, NM 87532	Advanced Cleaning & Advanced Inspection W.L. Gore Black Crosstech Type 2F Moisture Barrier
Deering Cleaners 602 N. Capitol Ave. Indianapolis, IN 46240	Advanced Cleaning & Advanced Inspection
Dollar Fifty Cleaners 1005 W. Nolana Suite C McAllen, TX 78504	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier
Done Right Fire Gear Repair 7621 Maryland Ave. Hudson, Florida 34667	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
<p>Don's Leather Cleaning. Inc. 3713 East Lake Street Minneapolis, MN 55406</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell</p>
<p>ECMS, Inc. 16821 Knott Ave. La Mirada, CA 92638</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>
<p>ECMS, Inc. 4200 West Russell Road, Suite 113 Las Vegas, NV 89118</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier Stedfast Stedair 3000 Moisture Barrier</p>
<p>ECMS, Inc. 1809 Perlata Street Oakland, CA 94607</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier</p>
<p>ECMS, Inc. 4647 South 33rd Street Phoenix, AZ 85040</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
<p>ECMS, Inc. – Salt Lake City 1185 South 300 West Salt Lake City, UT 84101</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>
<p>ECMS, Inc. 629 South Industrial Way Seattle, WA 98108</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>
<p>Elite Uniforms, Inc. 11416 Kiley Dr. Huntley, IL 60142</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner</p>
<p>Fire Safety Services Inc 6228 Road 95 Huntsville, OH 43324</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>Fire Service Management Calgary 7042 - 30th Street SE Calgary AB T2C 1N9</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
Fire W.I.R.E. LLC 813 EL Serrano CT SW Albuquerque, NM 87105	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier
Fort Worth Fire Department (Organization) 2900 W. Bolt St. Fort Worth, TX 76110	Advanced Cleaning & Advanced Inspection Outer Shell - PBI Matrix (Gemini) Thermal Liner - Quantum 3D W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Georgian Firegear Service 103 Bayfield Street Barrie Ontario Canada QC L4M 3A9	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier
Gloves, Inc. 1950 Collins Blvd. Austell, GA 30106	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Gloves, Inc. 8745 NW 100th St. Medley, FL 33178	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier Stedfast Stedair 4000 Moisture Barrier

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
Insurance Restoration Specialists 30 Abeel Road Monroe Township, NJ 08831	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner
Isotech Instrumentation, Inc. 2250, Andre C. Hamel Drummondville QC J2C 8B1	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Maryland Fire Equipment 12284 Wilkins Avenue Rockville, MD 20852	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier
Minerva Bunker Gear Cleaners 780 East 134th Street Bronx, NY 10454	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Minerva Bunker Gear Cleaners Corp. EIN#45-4661121 3839 Corporation Circle Charlotte, NC 28216	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
<p>MBGC LLC d/b/a Minerva Bunker Gear Cleaner 3795 NW 38 St. Miami, FL 33142</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>PPE Care 2650 Old Louetta Loop #8 Spring, TX 77388</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>Rainbow Cleaners 44 Queen Anne Road Bogota, NJ 07603</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner</p>
<p>Scott's PPE Recon 827 Black Diamond Way, Buliding C Lodi, CA 95240</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier</p>
<p>Shamrock Gear &amp; Repair LLC 5824 Akron Cleveland Road Boston Hts, OH 44236</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 3000 Moisture Barrier</p>



# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
Solutions of New Orleans 4929 E. Judge Perez Drive Violet, LA 70092	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
The Fire Industry Repair & Maintenance Building C #5 624 Beaver Dam Road NE Calgary AB Canada T2K 4W6	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Turnout Maintenance Co. 7734 Garden Grove Westminster, CA 92683	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the physical address identified above and is not applicable for any mobile unit(s) or address(es) not listed. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Trevor O'Gorman at [trevor.ogorman@intertek.com](mailto:trevor.ogorman@intertek.com)  
Revision Date: 1/26/2016